



Sample Report

Project Name: Example Inspection

Date: February 21, 2025

Prepared By: Bob Smith



Photo 1: Curb repair complete. Intersection of Koala St. and Kangaroo Ave.



Photo 2: Cracks spreading on Emu Pl.




Photo 3: Footpath on Wombat Cl. needs repair (trip hazard).



Photo 4: Footpath on Kookaburra St. looks fine.



Photo 5: Footpath on Possum Rd. looks good too.